





Mooring problems with very large Mooring problems with very large container vessels container vessels Problem : Guidelines - Recommendations : > OCIMF Mooring Equipment Guidelines (1997) > High sides 2nd edition. New edition spring 2008 > Very high bow Mooring only bow/stern > IACS Requirement A2/2004 (Rev.3/2007) Position bollards "Shipboard fittings and supporting hull structures associated with towing and mooring on conventional vessels Very steep mooring lines with poor angle for Typical mooring : 4+2 or 4+1+2 maximum tension 5 6









3